

Trailer Condition Report:

Equipment Information:

Unit No: TM8829
Year: 2004
Make: Lufkin
Model: FL-11
VIN/SN: 1L01B422X41153829

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Physical Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: 80,000
Tire Size: 295/75R22.5
Braking:

Suspension: _____
Sliding Tandem Axle: _____

Comments: rust issues and wood deck is worn

Deck

Hitch Type: Kingpin
Dimensions: Length: 45' Width: 102"
Ramps (if equipped): _____

Specialized Equipment:

Type: _____
Type: _____

Details: _____
Details: _____

Notes: _____
Notes: _____