

Trailer Condition Report:

Equipment Information:

Unit No: TM9066
Year: 2004
Make: Lufkin
Model: _____
VIN/SN: 1L01B452641154066

Miles/Hrs.:

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair
Interior Condition: Fair - Functioning, but in need of repair
Exterior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: _____ Suspension: Spring
Tire Size: 285/75R24.5 Sliding Tandem Axle: _____
Braking: _____

Comments: Evidence of previous tire blow outs. Wood deck damaged. Rust corrosion near neck.

Deck

Hitch Type: Kingpin
Dimensions: Length: 45' Width: 102"
Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____
Type: _____ Details: _____

Notes: _____

Notes: _____