

CONDITION REPORT FOR MISC. EQUIPMENT

Location	<u>Ft Meade Main Express</u>	Year	<u>2016</u>	Hours	<u></u>
Facility #	<u>0206140700</u>	Make	<u>Southern CaseArts</u>		
Address	<u>4706 MacArthur Rd</u> <u>Ft. Meade, MD 20755</u>	Model	<u>MDI-03VN</u>		
POC	<u>Sharon Althoff</u>	Serial #	<u>SN16-009444</u>		
Email	<u>althoffs@aafes.com</u>	FA #	<u>0206300234</u>		
Telephone	<u>410-674-4540</u>	Type of Equipment	<u>Island Cooler</u>		
Facility # To Credit	<u>0206140700</u>	Best Days & Time to View	<u>M-F 8am – 3 pm EST</u>		

TYPE OF SALE**Useable**

Repairable

Salvage

Scrap

Does Equipment Contain Freon Gas
NoMust Gas Be Removed Prior to Transport?
N/A

Power Source	<u>Electric</u>	Amps	<u>22.91</u>	Volts	<u>208-230 3 wire</u>
Other Utility Hook Ups <u></u>					

CONDITION OF EQUIPMENT

	Good	Fair	Poor	Explain
Function	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Cooling temperature holds steady
Appearance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Very good condition with screens
Safety	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

DETAILED DESCRIPTION OF EQUIPMENT

Very nice Island cooler. Three cooling shelves with additions merchandising space on top and around lower perimeter of island. Screens for both sides are intact with no damage. Unit cools well and holds a consistent temperature.

INFORMATION REGARDING REMOVAL

Unit is NOT on wheels. Can be taken out thru double doors for easier removal from building. Some type of pallet jack or dolly will be needed for removal.

Additional Comments

--