

# Vehicle Inspection Form

Inventory ID: \_\_\_\_\_

Asset Number: \_\_\_\_\_

Fair Market Value: \_\_\_\_\_

**Short Description:**

Year 2020 Make RAM Model Tradesman 1500

VIN: 1C6SRFGT4LN227756 Title: ☒ Clean Title ☐ Salvage Title ☐ No Title  
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: 99,122 ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☐ Yes ☐ No ☐ Unknown

**Long Description:**

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 5.7 L, V ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: \_\_\_\_\_

This vehicle was maintained every 5,000 ☐ Days ☐ Hours ☒ Miles/Kilometers

Date Removed from Service: \_\_\_\_\_ Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: \_\_\_\_\_

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: \_\_\_\_\_

**Exterior:** Color: White Windows: ☐ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: \_\_\_\_\_ Tread: \_\_\_\_\_ #Flat \_\_\_\_\_ Hubcaps # \_\_\_\_\_

Major Damage to: \_\_\_\_\_

Additional Damage: \_\_\_\_\_

Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

**Interior:** Color Grey ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: \_\_\_\_\_

Damage to Dash/Floor: \_\_\_\_\_

Radio: ☒ Stock or ☐ Brand & Model: \_\_\_\_\_ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☒ Cold ☐ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual

☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

**Additional Equipment:** Strobe lights

Manufacturer \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand \_\_\_\_\_ ☐ Hitch: Type \_\_\_\_\_

Location of Asset: 145 Rosewood Dr. Lyman SC 29365