

# Boom Truck Condition Report:

## Equipment Information:

**Unit No:** WB7505 **Engine Information:**  
**Year:** 2011 **Year:** 2011  
**Make:** Kenworth **Make:** Caterpillar **HP:** 475  
**Model:** T800 **Model:** C 13 ACERT  
**VIN/SN:** 1NKDLU0X1BJ946505 **SN:** N/A  
**Miles/Hrs.:** 334185 KMS / 13939.8 HRS **Fuel Type:** Diesel

## Equipment Condition:

**Mechanical Condition:** Very Good - Starts and operates with no known mechanical defects.  
**Interior Condition:** Good - Damage is limited to normal wear and minor scratches.  
**Exterior Condition:** Good - Minor dings and scratches  
**AC/Heat Functional:** Yes  
**Leaks Present:** Not Seen **Engine Displacement:** 12.0L **Number of Cylinders:** 6  
**Sleeper (if Applicable):** **Length:** N/A **# of Bunks:** N/A **Aux Power Unit?**   
**Additional Equipment:** Operator admits Heat work very well, AC is not very cold, may require repair.

## Transmission:

**Transmission Make:** Eaton Fuller  
**Auto / Manual:** Manual **Number of Speeds:** 18  
**Truck Moves FWD/REV:** Both  
**Comments:** No known major leaks or issue with transmission or motor.

## Chassis:

**Frame Rails:** Double **Notes:**   
**Suspension:** Air **Notes:** rear is Air, front is Springs  
**Wheel Base:**  **in.**   
**Axle Weight Ratings (LBS):** **GVWR:** 66,000 **Front Axel:** 20,000 **Rear(s):** 23,000  
**Tire Size:** **Front:** 425 / 66 R 22.5 **Rear(s):** 11 R 22.5  
**Comments:** Frame rails and underbody has some paint chips / rust spots from normal operation.

## Flatbed

**Bed Dimensions:** **Length:** 23'9" **ft.** **Width:** 8'6" **ft.**  
**Conveyor/Boom Make:** HIAB SN# 435001 **Conveyor/Boom Model:** 435 HI PRO  
**Conveyor/Boom Is Functional:** Yes

### Additional Notes:

The boom operates effectively in a fully extended position and is equipped with pallet forks