

Trailer Condition Report:

Equipment Information:

Unit No: TL7536
Year: 2006
Make: Asetrail
Model: _____
VIN/SN: 2A9P4B4376E061536

Equipment Condition:

Mechanical Condition: Very Good - No Known Mechanical Defects

Interior Condition: Good - Some Parts May Require Repair or Replacement Soon

Chassis:

GVWR: 25,000 Suspension: Air
Tire Size: 11R22.5 Sliding Tandem Axle: No
Braking: Air
Comments: _____

Deck

Hitch Type: Pentle
Dimensions: _____ Length: 28Ft Width: 8Ft
Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____
Type: _____ Details: _____

Notes: _____

Notes: _____