

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Dump Truck

Other: _____

Unit No: 15.2514

Year: 2018

Make: Mack

Model: GU713

VIN/SN: 1M2AX07C5JM037101

Miles/Hrs.: 326213

Engine Information:

Year: 2018

Make: Mack

Model: MP8

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional:

Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate

Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes

AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: Front: 385/65R22.5

Rear(s): 11R24.5

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: