

# Vehicle Condition Report:

## Vehicle Information:

**Vehicle Type:** Work Truck

**Other:** \_\_\_\_\_

**Unit No:** 15.06036

### Engine Information:

**Year:** 2018

**Year:** 2018

**Make:** Dodge

**Make:** Cummins

**Model:** Ram5500

**Model:** \_\_\_\_\_

**VIN/SN:** 3C7WRNBL4JG110389

**SN:** \_\_\_\_\_

**Miles:** 288203

**Fuel Type:** Diesel

## Vehicle Condition:

**Mechanical Condition:** Good - Starts and operates; Some parts may require repair or replacement soon.

**Interior Condition:** Fair - Interior is heavily worn.

**Exterior Condition:** Good - Minor dings and scratches

**Condition Comments:** \_\_\_\_\_

**Engine Displacement:** 6.7 **Liters. Crankshaft (V, Inline, Boxer)** \_\_\_\_\_ **Cylinders:** 6

**Power Windows:** No **Power Locks:** \_\_\_\_\_

**Air Conditioner / Heat:** Yes **AC / Heat Functional:** \_\_\_\_\_

**Transmission:** Automatic **Number of Manual Speeds:** \_\_\_\_\_

**Unit Moves FWD/REV:** Both

**Functional:** \_\_\_\_\_

**Four Wheel Drive (4x4):** Yes

**Additional Equipment:** Venturo Crane HT40KXX

## Chassis:

**Suspension:** Spring **Notes:** \_\_\_\_\_

**Wheelbase:** \_\_\_\_\_ **GVWR:** 19500 **Front:** 7000 **Rear(s):** 13500

**Tire Size:** \_\_\_\_\_ **Front:** 225/70R19.5G **Rear:** 225/70R19.5G

**Comments:** \_\_\_\_\_

## Cargo / Passenger Vans

**Passenger Van Seating:** \_\_\_\_\_ **Rows:** \_\_\_\_\_

**Cargo Van Box Dimensions:** \_\_\_\_\_ **Length:** \_\_\_\_\_ **Width:** \_\_\_\_\_ **Height:** \_\_\_\_\_

**Additional Notes:** \_\_\_\_\_