

# Truck Tractor Condition Report:

## Equipment Information:

Unit No:	15.21021	Engine Information:	<b>Starts and Runs:</b>	<b>Yes</b>			
Year:	2018	Year:	2017				
Make:	Peterbilt	Make:	PACCAR				
Model:	337	Axle:	Single	Model:	PX-7	HP:	
VIN/SN:	2NP2HM7X5JM467147		SN:				
KM/Hrs.:	93281	Fuel Type:	Diesel				

## Equipment Condition:

**Mechanical Condition:** Good - Starts and operates; Some parts may require repair or replacement soon.

**Interior Condition:** Fair - Interior is heavily worn.

**Exterior Condition:** Fair - Visible dents and scratches

**AC/Heat Functional:** Yes

**Leaks Present:** Not Seen    **Engine Displacement:** 6.7    **Number of Cylinders:** 6

**Sleeper (if Applicable):** Length:    # of Bunks:    **Aux Power Unit?**

**Additional Equipment:**

## Transmission:

**Transmission Make:** Allison

**Auto / Manual:** Automatic    **Number of Speeds:**

**Truck Moves FWD/REV:**

**Comments:**  
dash area is tore up

## Chassis:

**Frame Rails:**    **Notes:**

**Suspension:** Spring    **Notes:**

**Wheel Base:**    in.

**Axle Weight Ratings (LBS):**    **GVWR:** 33,000    **Front Axel:**    **Rear(s):**

**Tire Size:**    **Front:** 11R22.5    **Rear(s):** 11R22.5

**Comments:**

## Specialized Equipment:

**Type:** Leeboy tank    **Details:**

**Type:**    **Details:**

**Notes:**

**Notes:**