

Dump Truck Condition Report:

Equipment Information:

Unit No: 15.25139
Year: 2018
Make: Mack
Model: GU713 Axle: Tri/Axle
VIN/SN: 1M2AX07C7JM037102
KM/Hrs.: 311324

Engine Information: Starts and Runs: Yes
Year: 2018
Make: Mack
Model: MP8 HP:
SN: Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional:

Leaks Present: Engine Displacement: 12.7 Number of Cylinders 6

Sleeper (if Applicable): Length: # of Bunks: Aux Power Unit?

Additional Equipment:

Transmission:

Transmission Make: MaxTorque

Auto / Manual: Manual Number of Speeds: 8

Truck Moves FWD/REV: Both

Comments:

Chassis:

Frame Rails: Notes:

Suspension: Air Notes:

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: Front Axle: Rear(s):

Tire Size: Front: 385/65R22.5 Rear(s): 11R24.5

Comments:

Specialized Equipment:

Type: Details:

Type: Details:

Notes:

Notes: