

Truck Tractor Condition Report:

Equipment Information:

Unit No: 15.30049
Year: 1995
Make: Peterbilt
Model: 379 Axle: Tri/Axle
VIN/SN: 1XP5DB8X6SD365980
KM/Hrs.: 448911

Engine Information: Starts and Runs: Yes
Year: _____
Make: CAT
Model: 3406 HP: _____
SN: _____
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 14.6 Number of Cylinders 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Eaton

Auto / Manual: Manual Number of Speeds: 8

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: Single Notes: _____

Suspension: Spring Notes: _____

Wheel Base: in. _____

Axle Weight Ratings (LBS): GVWR: 46,000 Front Axle: 12,000 Rear(s): 34,000

Tire Size: Front: 11R22.5 Rear(s): 255/70R22.5

Comments: _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____