Trailer Condition Report:

		Equipii	ient imormati	JII.	
Unit No:	15.40206				
Year:	2019				
Make:	Bye-Rite				
Model:					
VIN/SN:	7F3B1UK21KR002280				
Miles/Hrs.:					
		Equip	ment Conditio	n:	
Mechanical Condition:		Fair - Functioning, but	t in need of repair		
Interior Condition:		Fair - Functioning, but in need of repair			
Exterior Condition:		Fair - Functioning, but in need of repair			
			Chassis:		
GVWR:		14,000 S		Suspension:	
Tire Size:		ST235/80R16		Sliding Tandem Axle:	
Braking:					
Comments:		sides are warped			
Deck					
	Hitch Type:	Ball			
	Dimensions:	Length:	20'	Width: 7'	
Ramps (if equipped)		Beavertail			
	·				
		Specia	lized Equipme	nt:	
Type:			Details:		
Type:		_	Details:		
Notes:					
Notes:					