

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other:

Unit No: 15.46122

Engine Information:

Year: 2018

Year: 2018

Make: John Deere

Make:

Model: 524K

Model:

HP:

VIN/SN: 1DW524KZEJF685894

SN:

Miles/Hrs.:

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional:

No

Hydraulic Leaks Present: No

Unit Moves FWD/REV:

Neither

All Attachments Articulate

No

Notes:

Control Station Type: Enclosed Cab

AC/Heat:

Yes

AC/Heat working:

Could not confirm

Additional Equipment:

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition:

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: Front: 20.5R25

Rear(s): 20.5R25

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe:

Type:

Details:

Type:

Details:

Additional Notes:

doesn't run, had been vandalized, a couple of electronic stolen of engine compartment, wires damaged, door torn off