

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: 15.46136

Year: 2018

Make: Komatsu

Model: WA320-8

VIN/SN: KMTWA135HHNA38261

Miles/Hrs.: 23749/11042

Engine Information:

Year: 2018

Make: Komatsu

Model: 6.69L

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Yes

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: _____

Front: 20.5R25

Rear(s): 20.5R25

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: