

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Excavator

Other: _____

Unit No: 15.51106

Year: 2014

Make: Bobcat

Model: E26

VIN/SN: B33211303

Miles/Hrs.: 3073

Engine Information:

Year: 2014

Make: Kubota

Model: D1803-M-DI-E4

HP: 24.8

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Canopy

AC/Heat: No

AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: _____

Propulsion Type: Track, Rubber

Track Condition: Good - Track condition shows normal wear from use

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: