## **Heavy Equipment Condition Report:**

	ASSE	et iiiioiiiiat	1011.		
Equipment Type:	Excavator				
Other:					
Unit No: 15.51062			1	Engine Information:	
<b>Year:</b> 2016		Year:	2016		
Make: John Deere		Make:			
Model: 35G		Model:			HP:
VIN/SN: 286192		SN:			
Miles/Hrs.: 3452		Fuel Type:	Diesel		
Asset Condition:					
Mechanical Condition:	Good - Starts and operates; Some parts may require repair or replacement soon.				
Interior Condition:	Fair - Interior is heav	Fair - Interior is heavily worn.			
Exterior Condition:	Fair - Visible dents and scratches				
Hydraulics are Functional:	Yes <b>Hydraulic Leaks Present:</b> No				
Unit Moves FWD/REV:	Both				
All Attachments Articulate	Yes	Notes:			
Control Station Type:	Enclosed Cab	AC/Heat:	No	AC/Heat working:	N/A
Additional Equipment:		-		_	
		<b>Chassis:</b>			
Powertrain Type:					
Propulsion Type:	Track, Rubber				
Track Condition:	Fair - Track condition shows heavy use and may require maintenance				
Wheel Condition:					
Tire Size:	Front: Rear(s):				
Attachments					
Are there additional attachments that are not currently connected to this asset?					
Describe:					
Туре:		Details:			
Туре:	Details:				
Additional Notes:					