

# Heavy Equipment Condition Report:

## Asset Information:

Equipment Type: \_\_\_\_\_

Other: Compactor

Unit No: 15.53112

Year: 2006

Make: Caterpillar

Model: CB-344 II

VIN/SN: C3A00120

Miles/Hrs.: 3438

Engine Information:

Year: 2006

Make: \_\_\_\_\_

Model: \_\_\_\_\_

SN: \_\_\_\_\_

HP: \_\_\_\_\_

Fuel Type: Diesel

## Asset Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: \_\_\_\_\_

Control Station Type: Canopy

AC/Heat: No

AC/Heat working: \_\_\_\_\_

Additional Equipment: \_\_\_\_\_

## Chassis:

Powertrain Type: \_\_\_\_\_

Propulsion Type: \_\_\_\_\_

Track Condition: \_\_\_\_\_

Wheel Condition: \_\_\_\_\_

Tire Size:

Front: \_\_\_\_\_

Rear(s): \_\_\_\_\_

## Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

## Additional Notes:

rollers are 51" X 30"