

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: _____

Other: Sweeper

Unit No: 15.57041

Year: 2010

Make: Rosco

Model: Sweep Pro 4830

VIN/SN: 60378

Miles/Hrs.: 16025

Engine Information:

Year: _____

Make: _____

Model: _____

SN: _____

HP: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 2WD

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size:

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: