

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Excavator

Other: _____

Unit No: 15.51061

Year: 2016

Make: John Deere

Model: 50G

VIN/SN: 283595

Miles/Hrs.: can't read

Engine Information:

Year: _____

Make: Yanmar

Model: _____ HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate Yes

Notes: _____

Control Station Type: Canopy

AC/Heat: No AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: _____

Propulsion Type: Track, Rubber

Track Condition: Fair - Track condition shows heavy use and may require maintenance

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: