

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Excavator

Other: _____

Unit No: 15.5113

Year: 2015

Make: John Deere

Model: 85G

VIN/SN: 1FF085GXJFJ018136

Miles/Hrs.: _____

Engine Information:

Year: 2015

Make: Yanmar

Model: Tier 4

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: No

Hydraulic Leaks Present: _____

Unit Moves FWD/REV: Neither

All Attachments Articulate: No

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: No

Additional Equipment: _____

Chassis:

Powertrain Type: _____

Propulsion Type: Track, Rubber

Track Condition: Fair - Track condition shows heavy use and may require maintenance

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

Will not start and run, possible hydraulic issues