

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Dozer

Other: _____

Unit No: 45957

Year: 2017

Make: Komatsu

Model: D37PX-24

VIN/SN: KMT0D131LGA085057

Miles/Hrs.: 4182

Engine Information:

Year: 2017

Make: Komatsu

Model: _____

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Could not confirm

Additional Equipment: _____

Chassis:

Powertrain Type: _____

Propulsion Type: Track, Metal

Track Condition: Fair - Track condition shows heavy use and may require maintenance

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: