

Truck Tractor Condition Report:

Equipment Information:

Unit No:		Engine Information:	
Year:	2010	Year:	
Make:	Mack	Make:	MACK
Model:	MRU613	Model:	MP7
VIN/SN:	1M2AV02C7AM007224	SN:	9420285
KM/Hrs.:	22900	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: ☐ **Engine Displacement:** 10.8 **Number of Cylinders** 6

Sleeper (if Applicable): Length: **# of Bunks:** **Aux Power Unit?**

Additional Equipment:

Transmission:

Transmission Make: ALLISON

Auto / Manual: Automatic **Number of Speeds:** 6

Truck Moves FWD/REV: Both

Comments:

Chassis:

Frame Rails: Double **Notes:** Surface rust starting

Suspension: Air **Notes:**

Wheel Base: 230 in.

Axle Weight Ratings (LBS): GVWR: 66,000 **Front Axel:** 20,000 **Rear(s):** 46,000 tandem

Tire Size: Front: 315/80R22.5 **Rear(s):** 11R22.5

Comments:

Specialized Equipment:

Type: McNeilus AutoReach **Details:** 30-40 yards

Type: **Details:**

Notes: Unit has air leak in cab, and underneath left side, middle

Notes: