

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Boom lift

Other: _____

Unit No: 16006

Year: 2013

Make: Genie

Model: Z45/22

VIN/SN: 40707520

Miles/Hrs.: 3463

Engine Information:

Year: 2013

Make: Ford

Model: LRG-4231-6007-B

HP: _____

SN: 0059 G-05-RT

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: No

Hydraulic Leaks Present: Could not confirm

Unit Moves FWD/REV: Neither

All Attachments Articulate: No

Notes: _____

Control Station Type: None

AC/Heat: No AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: