

Truck Tractor Condition Report:

Equipment Information:

Unit No: 89600

Year: 2012

Make: Kenworth

Model: T800

VIN/SN: 1XKDDP9X5CR321986

KM/Hrs.: 543274

Engine Information:

Year: 2012

Make: PACCAR

Model: MX-13

SN:

HP:

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen

Engine Displacement: 12.9

Number of Cylinders 6

Sleeper (if Applicable): Length:

of Bunks:

Aux Power Unit?

Additional Equipment:

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual

Number of Speeds: 10

Truck Moves FWD/REV: Both

Comments:

Performed 90 day inspection on 5/7/2025.

Worn Fuel Tank Liners. irregular wear on steer tires. small air leaks. small crack on windshield. right hood mirror loose. small power steering leak. small oil leak on left side of motor.

Chassis:

Frame Rails: Double

Notes:

Suspension: Air

Notes:

Wheel Base: in.

Axle Weight Ratings (LBS):

GVWR: 52,000

Front Axel: 12,000

Rear(s): 40,000

Tire Size: Front: 75R24.5

Rear(s): 75R24.5

Comments:

Specialized Equipment:

Type:

Details:

Type:

Details: