

Truck Tractor Condition Report:

Equipment Information:

Unit No:	89619	Engine Information:	
Year:	2014	Year:	2014
Make:	Kenworth	Make:	PACCAR
Model:	T800	Model:	MX-13
VIN/SN:	1XKDDP9X2ER390945	SN:	
KM/Hrs.:	371226	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen

Engine Displacement: 12.9

Number of Cylinders 6

Sleeper (if Applicable): Length:

of Bunks:

Aux Power Unit?

Additional Equipment:

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual

Number of Speeds: 10

Truck Moves FWD/REV: Both

Comments: Performed 90 day inspection on 5/5/2025. air leaks when brakes applied. mv3 knobs ye

Chassis:

Frame Rails: Single

Notes:

Suspension: Air

Notes:

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: 52,000 Front Axel: 12,000 Rear(s): 40,000

Tire Size: Front: 75R24.5

Rear(s): 75R24.5

Comments:

Specialized Equipment:

Type:

Details:

Type:

Details:

Notes: #REF!

Notes: #REF!