Trailer Condition Report:

| | | Equipi | nent informatio | 11. | | |
|------------------------|-------------------------------|--|-----------------------|----------------------|--------|---|
| Unit No: | 50C109 | | | | | |
| Year: | 2014 | | | | | |
| Make: | Utility Trailer Manufacturing | | | | | |
| Model: | TS2CHA | | | | | |
| VIN/SN: | 1UYTS250SFA31 | 8602 | | | | |
| Equipment Condition: | | | | | | |
| Mechanical Condition: | | Good - Some Parts May Require Repair or Replacement Soon | | | | |
| Inte | erior Condition: | Good - Some Parts M | lay Require Repair or | r Replacement So | oon | |
| Chassis: | | | | | | |
| GVWR: | | 65,000 | | Suspension: | Air | |
| Tire Size: | | 285/75R24.5 | | Sliding Tandem Axle: | | |
| Braking: | | Air | | | | |
| | Comments: | | | | | |
| Deck | | | | | | |
| | Hitch Type: | Kingpin | | | | |
| Dimensions: | | Length: | 50 | | Width: | 8 |
| Ramps | (if equipped) | | | | | |
| | | | | | | |
| Specialized Equipment: | | | | | | |
| Type: | | | Details: | | | |
| Type: | | | Details: | | | |
| Notes: | | | | | | |