Truck Tractor Condition Report:

		Equip	ment infor	mation.				
Unit No: 89664	89664 Engine Information:							
Year: 2016			Year:					
Make: Kenworth			Make:	Paccar				
Model: T880			Model:	MX/MX-1	13	HP:		
VIN/SN:			SN:					
KM/Hrs.: 595128			Fuel Type:	Diesel				
Equipment Condition:								
Mechanical Condition:	cal Condition: Good - Starts and operates; Some parts may require repair or replacement soon.							
Interior Condition:	Good - Da	mage is li	mited to norma	al wear and	l minor scra	tches.		
Exterior Condition:	Good - Mi	nor dings	and scratches					
AC/Heat Functional:	Yes							
Leaks Present:	Not Seen	Engine D	isplacement:	12.9		er of Cylinders	6	
Sleeper (if Applicable):	Length:		_# of Bunks:		Aux	Power Unit?		
Additional Equipment:								
•								
			Transmissio	n:				
Transmission Make:								
Auto / Manual:	Manual				Number o	f Speeds: 10		
Truck Moves FWD/REV:	Both							
Comments:								
			Chassis:					
Frame Rails:	Single				Notes:			
Suspension:	Spring				Notes:			
Wheel Base:			in.		•			
Axle Weight Ratings (LBS):	GVWR:	63,370	Front Axel:	12,350		Rear(s): 40,000		
Tire Size:	Front:				Rear(s):			
Comments:					-			
		Spec	ialized Equi	pment:				
Гуре:			Details:					
Гуре:			_Details:					
Notes:								
Notes:								