

Truck Tractor Condition Report:

Equipment Information:

Unit No:	89634	Engine Information:	
Year:	2014	Year:	2014
Make:	Kenworth	Make:	PACCAR
Model:	T800	Model:	MX-13
VIN/SN:	1XKDDP9XXEJ399990	HP:	
KM/Hrs.:	721529	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition:	Good - Starts and operates; Some parts may require repair or replacement soon.		
Interior Condition:	Good - Damage is limited to normal wear and minor scratches.		
Exterior Condition:	Good - Minor dings and scratches		
AC/Heat Functional:			
Leaks Present:	Not Seen	Engine Displacement:	12.9
		Number of Cylinders	6
Sleeper (if Applicable):	Length:	# of Bunks:	
Additional Equipment:			

Transmission:

Transmission Make:	Eaton Fuller	
Auto / Manual:	Manual	Number of Speeds: 10
Truck Moves FWD/REV:	Both	
Comments:		

Chassis:

Frame Rails:	Single	Notes:	
Suspension:	Air	Notes:	
Wheel Base:		in.	
Axle Weight Ratings (LBS):	GVWR: 52,000	Front Axel: 12,000	Rear(s): 40,000
	Tire Size: Front: 75R24.5	Rear(s): 75R24.5	
Comments:			

Specialized Equipment:

Type:		Details:	
Type:		Details:	
Notes:			
Notes:			