

Truck Tractor Condition Report:

Equipment Information:

Unit No:	89598	Engine Information:	
Year:	2012	Year:	
Make:	Kenworth	Make:	Paccar
Model:	T800	Model:	MX
VIN/SN:	1XKDDP9X5CJ308685	SN:	
KM/Hrs.:	391361	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition:	Fair - Starts and operates but some parts require repair or replacement.		
Interior Condition:	Fair - Interior is heavily worn.		
Exterior Condition:	Fair - Visible dents and scratches		
AC/Heat Functional:	Yes		
Leaks Present:	Not Seen	Engine Displacement:	12.9
Sleeper (if Applicable):	Length:	# of Bunks:	
Additional Equipment:		Number of Cylinders:	6
		Aux Power Unit?	

Transmission:

Transmission Make:	Eaton Fuller	
Auto / Manual:	Manual	Number of Speeds:
Truck Moves FWD/REV:	Both	10
Comments:	repeated DEF issues	

Chassis:

Frame Rails:	Single	Notes:	
Suspension:	Air	Notes:	
Wheel Base:		in.	
Axle Weight Ratings (LBS):	GVWR:	52,000	Front Axel:
		12,000	Rear(s):
	Tire Size:	Front:	75R24.5
		Rear(s):	75R24.5
Comments:			

Specialized Equipment:

Type:		Details:	
Type:		Details:	
Notes:			
Notes:			