

Truck Tractor Condition Report:

Equipment Information:

Unit No:	89628	Engine Information:	
Year:	2014	Year:	2014
Make:	Kenworth	Make:	PACCAR
Model:	T800	Model:	MX-13
VIN/SN:	1XKDDP9X3ER394261	SN:	Y025341
KM/Hrs.:	420367	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen **Engine Displacement:** 12.9 **Number of Cylinders** 6

Sleeper (if Applicable): Length: # of Bunks: Aux Power Unit?

Additional Equipment:

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual **Number of Speeds:** 10

Truck Moves FWD/REV: Both

Comments: Check engine code U41073 (humidity sensor)

Chassis:

Frame Rails: Single

Notes:

Suspension: Air

Notes:

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: 52,000 **Front Axel:** 12,000 **Rear(s):** 40,000

Tire Size: Front: 75R24.5 **Rear(s):** 75R24.5

Comments:

Specialized Equipment:

Type: **Details:**

Type: **Details:**

Notes:

Notes: