

Truck Tractor Condition Report:

Equipment Information:

Unit No:	89649	Engine Information:	
Year:	2015	Year:	2015
Make:	Kenworth	Make:	PACCAR
Model:	T800	Model:	MX-13
VIN/SN:	1XKDDP9X3FR444688	SN:	Y054153
KM/Hrs.:	303461/13615	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen

Engine Displacement: 12.9

Number of Cylinders 6

Sleeper (if Applicable): Length:

of Bunks:

Aux Power Unit?

Additional Equipment:

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual

Number of Speeds: 10

Truck Moves FWD/REV: Both

Comments: check engine codes P1026 (BPV actuator out of calibration) P1488 (EGR valve module out of calibration)

Chassis:

Frame Rails: Single

Notes:

Suspension: Air

Notes:

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: 52,000 Front Axel: 12,000 Rear(s): 40,000

Tire Size: Front: 75R24.5

Rear(s): 75R24.5

Comments:

Specialized Equipment:

Type: **Details:**

Type: **Details:**

Notes:

Notes: