

Truck Tractor Condition Report:

Equipment Information:

Unit No:	89641	Engine Information:	
Year:	2014	Year:	2013
Make:	Kenworth	Make:	PACCAR
Model:	T800	Model:	MX-13
VIN/SN:	1XKDDP9X5ER404949	SN:	Y029947
KM/Hrs.:	376944/18020	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen **Engine Displacement:** 12.9 **Number of Cylinders:** 6

Sleeper (if Applicable): Length: # of Bunks: Aux Power Unit?

Additional Equipment:

Transmission:

Transmission Make: Eaton Fuller

Auto / Manual: Manual **Number of Speeds:** 10

Truck Moves FWD/REV: Both

Comments:

Chassis:

Frame Rails: Single **Notes:**

Suspension: Air **Notes:**

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: 52,000 **Front Axel:** 12,000 **Rear(s):** 40,000

Tire Size: Front: 285/75R24.5 **Rear(s):** 285/75R24.5

Comments:

Specialized Equipment:

Type: **Details:**

Type: **Details:**

Notes:

Notes: