Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
		odel Silverado 1500 Hybrid
VIN: 36CXCUEJOAG214	Title: Clea	an Title Salvage Title No Title Occuments Only SF97 Form Other
Odometer: _ 96,030 [~		Odometer Accurate? Yes No Unknow
Long Description:		
		Engine Runs Does Not Run For Parts Only
		Propane/Natural Gas Gas/Electric Hybrid
	Needs repair is in unknown cor	idition
Repairs needed:		
This vehicle was maintained every		
	_	rds: Available Not Available For Inspection
	ManualSpeed Condition:	Operable Needs repair Is Unknown Condition
Repairs Needed:	1	
Drivetrain: 2 Wheel Drive	4 Wheel Drive Condition:	
Exterior: Color: White	Windows: No	Cracked Glass Cracked
		Tread: #Flat Hubcaps #
Major Damage to:		
Additional Damage:		
		oved & Impressions Remain No impressions are holes in the exterior There are no holes
Interior: Color	Cloth Vinyl	Leather
Damage to Seats:		
Damage to Dash/Floor:		
Radio: Stock or Brand & I	Model:	AM AM/FM AM/FM Cassette AM/FM CD
AC Condition: Cold	Unknown No AC	Air Bags: Driver's Side Dual
Cruise Control Tilt Steering	g Remote Mirrors Climate	Control
Power: Steering Window	vs Door Locks Seats	
Additional Equipment:		
Manufacturer	Model Se	erial #
Tool Box Light Bar La	dder Rack Utility Body: Brand	HHitch: Type
Location of Asset: 180 S	Western Ave Bra	Whey, ch 92227