

Vehicle Inspection Form

VH177 78

Inventory ID:

Asset Number:

Fair Market Value:

Short Description:

Year 2016 Make Dodge Model Charger

VIN: 2C3CDXA T4GH356304 Title: ☒ Clean Title ☐ Salvage Title ☐ No Title
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: 134,000 ☐ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☐ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 5.7 L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: Cam + lifters

This vehicle was maintained every 5,000 ☐ Days ☐ Hours ☒ Miles/Kilometers

Date Removed from Service: 04/2025 Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: Fair

Exterior: Color: Black Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: Fair Tread: Fair #Flat _____ Hubcaps # _____

Major Damage to: _____

Additional Damage: Missing front bumper

Decals: ☐ None ☒ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior: Color Black ☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: Fair condition

Damage to Dash/Floor: Fair condition

Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☒ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual

☒ Cruise Control ☐ Tilt Steering ☒ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: _____