

Vehicle Inspection Form

VH3016

79

Inventory ID:

Asset Number:

Fair Market Value:

Short Description:

Year 2014 Make Honda Model CRV

VIN: 2HKRM4H37EH662976 Title: ☐ Clean Title ☒ Salvage Title ☐ No Title
☐ Court Documents Only ☐ SF97 Form ☐ Other
 Odometer: 159315 ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☐ Runs/Drivable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: Engine rattles

This vehicle was maintained every 5000 ☐ Days ☐ Hours ☒ Miles/Kilometers

Date Removed from Service: 04/2025 Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☐ Operable ☐ Needs repair ☒ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: Fair

Exterior:

Color: Grey Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☐ Scratches ☐ Dings Tire Condition: _____ Tread: _____ #Flat _____ Hubcaps # _____

Major Damage to: Front end collision. Air bag released

Additional Damage: _____

Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior:

Color Grey ☐ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: Fair

Damage to Dash/Floor: Fair

Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☒ Unknown ☐ No AC

Air Bags: ☐ Driver's Side ☐ Dual

☒ Cruise Control ☐ Tilt Steering ☒ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

Additional Equipment:

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: _____