Vehicle Inspection Form

Inventory ID: Asset Number:	Fair Market Value:
Short Description:	Tan Murket Value.
xz 3 al / al al al	64500
VIN: \(\begin{aligned} \omega \text{B6GUCLXG1259753} \\ \omega \text{Title:} \text{Clean Title} \text{Salvage Title} \text{SF97 Form} \text{Other} \end{aligned} \)	
Odometer: 158 335	
Long Description:	
This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only	
Engine- Type: 6.6 L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid	
Engine Condition: Runs Needs repair is in unknown condition	
Repairs needed: Perts only	
This vehicle was maintained every 5,000 Days Hours Miles/Kilometers	
Date Removed from Service: 05/2025 Maintenance Records: Available Not Available For Inspection	
Transmission: Automatic Manual Speed Condition: Operable Weeds repair Wallshows Condition	
Repairs Needed: Parts only	
Drivetrain: 2 Wheel Drive Condition: Parts only	
Exterior: Color: Windows: No Cracked Glass Cracked	
Minor: Dents Scratches Dings Tire Condition: Poor Tread: Poor #Flat Hubcaps #	
Major Damage to: Perts only	
Additional Damage:	
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions	
There are holes in the exterior There are no holes	
Interior: Color Grey Cloth Vinyl Leather	
Damage to Seats: Poor conkition	
Damage to Dash/Floor: Puor conlition	
Radio: Stock or Brand & Model: AM AM/FM AM/FM Cassette AM/FM CD	
AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual	
Cruise Control Tilt Steering Remote Mirrors Climate Control	
Power: Steering Windows Door Locks Seats	
Additional Equipment:	
Manufacturer Model Serial #	
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type	
Location of Asset:	