

Vehicle Inspection Form

Inventory ID: IS0001032623	Asset Number: PDS-21-002839	Fair Market Value: \$300.00																	
Short Description: Year <u>2008</u> Make <u>Cadillac</u> Model <u>CTS</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 200px;"> <tr> <td>1</td><td>G</td><td>6</td><td>D</td><td>M</td><td>5</td><td>7</td><td>7</td><td>4</td><td>8</td><td>0</td><td>1</td><td>0</td><td>9</td><td>7</td><td>4</td><td>4</td> </tr> </table> Title Restriction: ☐ Y ☒ N			1	G	6	D	M	5	7	7	4	8	0	1	0	9	7	4	4
1	G	6	D	M	5	7	7	4	8	0	1	0	9	7	4	4			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr> <td> </td><td> </td><td> </td><td> </td><td> </td><td> </td> </tr> </table> ☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: _____																			
Long Description: This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☒ Does Not Run ☐ For Parts Only Engine- Type: <u> L, V6 </u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☐ Runs ☐ Needs repair ☒ is in unknown condition Repairs needed: <u>broken key in ignition and unknown mileage</u> This vehicle was maintained every <u>n/a</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u> </u> Speed Condition: ☐ Operable ☐ Needs repair ☒ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☐ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____																			
Exterior: Color: <u>Black</u> Windows: ☐ No Cracked Glass ☒ Cracked <u>Driver window broken</u> Minor: ☒ Dents ☒ Scratches ☐ Dings Tire Condition: <u>poor</u> Tread: <u> </u> #Flat <u> </u> Hubcaps # <u> </u> Major Damage to: <u>cracks in front bumper, crack in driver tail light,</u> Additional Damage: <u>other scratches and dents and dash is broken</u> Decals: ☐ None ☐ Have Been Sprayed <u>or</u> ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>black</u> ☐ Cloth ☐ Vinyl ☒ Leather Damage to Seats: <u>tears in driver seat</u> Damage to Dash/Floor: _____ Radio: ☐ Stock <u>or</u> ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☐ AC (Condition: ☐ Cold ☒ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats																			
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: <u>2000 Vassar St., Rm 110 Reno, NV 89502-2715</u> For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			