

**Vehicle/ Item Information**

Description: AWD Car Sedan Unit # 927 Vin #: 1FAHP2MK6HG113594  
Year: 2017 Make: FORD Model: TAURUS Mileage: 46,677  
Last day in service: 5/28/2025 Running condition: Operational Hours: 8,866

**Engine & Transmission Information**

Engine size: 3.7LIT. # of Cylinders: V-6 Type: GAS Brand: FORD  
Transmission Type: AUTO Model: \_\_\_\_\_ Speeds: 4SPD  
Oil change Interval: 350 Meter Type: GALLONS OF GAS  
Exterior Color: Black Interior Color: BLACK  
Police Package YES Titled as a Police Car YES

**Major Vehicle Equipment**

ABS brakes: ☒ Air Conditioning: ☒ AC Working: ☒ ☐ Yes No  
Air bags: ☒ ☒ Driver Pass Power Seat: ☐  
Am/Fm Radio : ☒ CD Player: ☒ Power Windows: ☒ Power Locks: ☒ Tilt Wheel: ☒  
Cruise Control: ☒ Rear Defroster ☒ Trunk Release ☐ E  
E-Electric M-Manual  
Front Wheel Dr. ☐ Four Wheel Dr. ☐ All Wheel Dr. ☒ Rear Wheel Dr. ☐

**Vehicle Condition**

Tires L R L L R R  
Tread Front:     Rear:     Size: Front P245/55R18  
Rear :     Rear :   Rear

Brake Types Front  DISC Rear:  DISC Rear :   
Brake Life Left Front  30% Rear:  20% Rear :

GVRW 5700LBS Front Axle: 3060LBS Rear Axle(s): 2680LBS

**Added Description and Accessories:**

2017 Ford Taurus Interceptor Police Package  
Additional dome light installed  
Equipment tray in truck  
Front Weather Tech floor liners  
Includes spare tire

**Known Defects:**

Various small dings dents and scratches on the body  
Decal residual  
Spot light has been removed  
Holes on interior panels from removed equipment  
Rear seats are included but no mounting hardware for the seats and seat belts  
Interior is dirty  
Rear interior door handles, door locks and window controls are inoperative  
Steering wheel cover is worn  
No center counsel  
B pillar trim is cut  
Fender strobe lights removed  
No rear floor liner  
Left dash vent is missing  
Hood paint is peeling  
Right headlamp is inoperative