

### Vehicle/ Item Information

Description: Car Sedan Unit # 979 Vin #: 2G1WD5E34E1150616  
Year: 2014 Make: CHEVY Model: IMPALA Mileage: 51,080  
Last day in service: 7/7/2025 Running condition: Operational

### Engine & Transmission Information

Engine size: 3.6 LIT. # of Cylinders: V-6 Type: GAS Brand: GM  
Transmission Type: Automatic Model: \_\_\_\_\_ Speeds: 4SPD  
Oil change Interval: 200 Meter Type: Gallons of Gas  
Exterior Color: Black Interior Color: Black  
Police Package Yes

### Major Vehicle Equipment

ABS brakes: ☒ Air Conditioning: ☒ AC Working: 

Yes	No
<input type="checkbox"/>	<input type="checkbox"/>

 Air bags: 

Driver	Pass- enger
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

 Power Seat: ☒  
Am/Fm Radio : ☒ CD Player: ☒ Power Windows: ☒ Power Locks: ☒ Tilt Wheel: ☒  
Cruise Control: ☒ Rear Defroster ☒ Trunk Release 

E
---

  
E-Electric M-Manual  
Front Wheel Drv ☒ Four Wheel Dr. ☐ All Wheel Dr. ☐ Rear Wheel Dr. ☐

### Vehicle Condition

Tires 

L	R
8/32	6/32

L	L
11/3	

R	R
	8/32

 Size: 

Front	P235/55R17
Rear	

  
Tread 

Front	
Rear	

Rear	
Rear	

Rear	
Rear	

  
BrakeTypes 

Front	DISC
Rear	DISC
Rear	

  
Brake Life Left 

Front	40%
Rear	30%
Rear	

  
GVRW 4,709 Front Axle: 2550 Rear Axle(s): 2159

### Added Description and Accessories:

2014 Chevy Impala with a 9C-1 Police package  
Additional dome light mounted  
Temporary spare included

### Known Defects:

Various small dents dings and scratches on the body  
Holes on the roof from removed equipment  
Interior is dirty  
Strobe lights mounted in backup light housings  
Holes on interior from removed equipment  
Rear speaker covers have holes from removed equipment  
Rear door handles, locks and window controls are inoperable  
Hole cut in trunk liner  
Steering wheel cover worn  
B pillar trim is cut  
Spot light has been removed  
Holes on mirror housing from removed strobe lights