

### Vehicle/ Item Information

Description: Car Sedan Unit # 993 Vin #: 2G1WD5E36D12254923  
Year: 2013 Make: CHEVY Model: IMPALA Mileage: 64,022  
Last day in service: 6/28/2025 Running condition: Operational

### Engine & Transmission Information

Engine size: 3.6 LIT. # of Cylinders: V-6 Type: GAS Brand: GM  
Transmission Type: Automatic Model: \_\_\_\_\_ Speeds: 4SPD  
Oil change Interval: 300 Meter Type: Gallons of Gas  
Exterior Color: Black Interior Color: Black  
Police Package Yes Titled as a Police Car Yes

### Major Vehicle Equipment

ABS brakes: ☒ Air Conditioning: ☒ AC Working: ☒ ☐ Yes No Air bags: ☒ ☒ Driver Pass-enger Power Seat: ☒  
Am/Fm Radio : ☒ CD Player: ☒ Power Windows: ☒ Power Locks: ☒ Tilt Wheel: ☒  
Cruise Control: ☒ Rear Defroster ☒ Trunk Release ☐ E  
E-Electric M-Manual  
Front Wheel Drv ☒ Four Wheel Dr. ☐ All Wheel Dr. ☐ Rear Wheel Dr. ☐

### Vehicle Condition

Tires L R L L R R  
Tread Front:     Rear:   Rear:   Size: Front P235/55R17  
Rear Rear:   Rear Rear:   Rear  
Brake Types Front  DISC Rear:  DISC Rear Rear:   
Brake Life Left Front  25% Rear:  25% Rear Rear:   
GVRW 4709lbs Front Axle: 2550lbs Rear Axle(s): 2159lbs

### Added Description and Accessories:

2013 Chevy Impala with a 9C-1 Police package  
Additional dome light mounted  
Temporary spare included

### Known Defects:

Various small dents dings and scratches on the body  
Holes on the roof from removed equipment  
Interior is dirty  
Strobe lights mounted in backup light housings  
Holes on interior from removed equipment  
Rear speaker covers have holes from removed equipment  
Rear door handles, locks and window controls are inoperable  
Hole cut in trunk liner  
Spot light has been removed  
Holes in mirror housings from removed strobe lights  
Holes in rear floor pans from drain holes  
Steering rack slight oil seepage  
Hole in front carpet