

Description:	<u>Cargo/Evidence Van</u>	Unit #	<u>1002</u>	Vin #:	<u>1FTNS24LX1HA05998</u>
Year:	<u>2001</u>	Make:	<u>FORD</u>	Model:	<u>E-250</u>
				Mileage:	<u>19,692</u>
Last day in service:	<u>10/26/2025</u>	Running condition:	<u>OPERATIONAL</u>	Hours:	<u></u>

Engine size:	5.4LIT.	# of Cylinders:	V-8	Type:	GAS	Brand:	FORD
Transmission Type:	AUTOMATIC	Model:		Speeds:			
Oil change Interval:	3000	Meter Type:	MILES				
Exterior Color:	WHITE	Interior Color:	GRAY				
Police Package		Titled as a Police Car					

ABS brakes:	☐	Air Conditioning:	☒	AC Working:	☒ Yes ☐ No	Air bags:	☒ Driver ☒ Pass	Power Seat:	☐
Am/Fm Radio :	☒	CD Player:	☐	Power Windows:	☐	Power Locks:	☐	Tilt Wheel:	☐
Cruise Control:	☐	Rear Defroster	☐	Trunk Release	☐				
				E-Electric M-Manual					
Front Wheel Dr.	☐	Four Wheel Dr.	☐	All Wheel Dr.	☐	Rear Wheel Dr.	☒		

Tires		L R Front: <table border="1"><tr><td>9/32</td><td>9/32</td></tr></table>		9/32	9/32	L L Rear: <table border="1"><tr><td>7/32</td><td></td></tr><tr><td></td><td></td></tr></table>		7/32				R R Rear: <table border="1"><tr><td></td><td>7/32</td></tr><tr><td></td><td></td></tr></table>			7/32			Size: Front LT225/75R16	
9/32	9/32																		
7/32																			
	7/32																		
Brake Types		Front	<table border="1"><tr><td>disc</td></tr></table>	disc	Rear:	<table border="1"><tr><td>disc</td></tr></table>	disc	Rear :		<table border="1"><tr><td></td></tr></table>									
disc																			
disc																			
Brake Life Left		Front	<table border="1"><tr><td>40%</td></tr></table>	40%	Rear:	<table border="1"><tr><td>40%</td></tr></table>	40%	Rear :		<table border="1"><tr><td></td></tr></table>									
40%																			
40%																			
GVWR 8600LBS		Front Axle: 3400LBS		Rear Axle(s):		5345LBS													

2001 Ford Econoline E-250 Van used as a evidence recovery Van

Fridge

Sink

120 Volt outlets

Red/Blue waring lights

Spot light

Spare tire

Shore line power is inoperative

Unable to test rear heater

Spot light is froze in position

holes on interior from removed equipment

Water system untested

Hinges on the side and rear doors are stiff

Various small dings and dents on the body

Some body rust and rear bumper rust

Needs front sway bar bushings