

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Backhoe

Other: _____

Unit No: _____

Engine Information:

Year: 2018

Year: _____

Make: Case

Make: _____

Model: 580 N EP

Model: _____

HP: _____

VIN/SN: JJGN58EPLJC750186

SN: 48136768

Miles/Hrs.: 7606

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Could not confirm

Hydraulic Leaks Present: Could not confirm

Unit Moves FWD/REV: Neither

All Attachments Articulate No

Notes: _____

Control Station Type: Canopy

AC/Heat: _____ AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 2WD

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

unit will start but has a bad engine knock, not safe to run