

Bus Inspection Form

Inventory ID 100273	Asset Number 37	Fair Market Value: 7500.00
Short Description: Year 2013 Make FORD Model TURTLETOP		
VIN: 1FDXE4FS4DDA45288 Mileage/Odometer: 240900 <input checked="" type="checkbox"/> Mi <input type="checkbox"/> Km <input type="checkbox"/> Hrs Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
Long Description: Primary use for Bus: STUDENT TRANSPORTATION # of Passengers: 18 / 2 WHEEL CHAIR This vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine Manufacture: FORD Engine Type: 6.8 L, V 20 <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine This Vehicle was maintained every 180 <input checked="" type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Repairs needed: RUNS FINE Date Removed From Service: 06/2025 Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available Transmission Manufacture: FORD <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Speed Transmission Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown Rebuilt (Date:) Repairs Needed: RUNS FINE Date Removed From Service: 06/2025 Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Exterior Description: Color: WHITE Windows: <input type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked Minor: <input checked="" type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: Low Flat Damage to: PLEASE LOOK AT THE PICTURES Additional Damage to: Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been Sprayed Over <input type="checkbox"/> Have been removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Other Exterior Information:		
Interior Description: Color <input type="checkbox"/> Vinyl <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Leather Damage to Seats: FAIRLY CLEAN Damage to Dash/Floor: NONE Radio: Brand <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD Air Conditioning: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No AC Operating Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown Other Interior Information/Options:		
Other Equipment: Description BRAUN WHEEL CHAIR LIFT Manufacturer Model Serial #		
Location of Asset:		