

Maintenance Inspection

Customer Name: [REDACTED] Phone: (H) [REDACTED]
 Service Advisor: [REDACTED] Technician: [REDACTED]
 VIN: JTDJT923585191761
 Vehicle Year/Model: 08 TOYOTA YARIS HATCH Printed: 04/07/2025 11:03:32
 Odometer: 143977
 RO: 164757 Tag:

INSPECTION RESULT - OK	WILL REQUIRE FURTHER ATTENTION	REQUIRES IMMEDIATE ATTENTION
------------------------	--------------------------------	------------------------------

Serviced

Inspect/Lubricate Hinges, Locks	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Inspect Differential Seals/Vents	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Inspect Transfer Case Seals/Vents	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Inspect Transmission Seals	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Propeller/Drive Shaft	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Front Brake Hoses and Lines	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Front Calipers	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Front Rotor Condition	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Front Pad Thickness	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Brake Hoses and Lines	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Calipers/Wheel Cylinders	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Rotor/Drum Condition	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Pad/Lining Thickness	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Rear Linkage, Springs, Cables	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Battery Tested and Condition	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Comment: Battery failed and needs to be replaced			
Shock Absorbers	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Steering Rack, Linkages & Boots	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Ball Joints/Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Drive Shaft Boots & Clamps	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Comment: Both front outer cv boots are torn and axles are making noise. Must replace both CV axles			

Brake Lining Measurements: LF: 5 mm RF: 5 mm LR: 2 mm RR: 2 mm
Tire Inspection Comment: Rear: back tires are too big for this vehicle
Tire Tread Measurements: LF: 7/32" RF: 7/32" LR: 7/32" RR: 7/32"
Tire Pressure Measurements: LF: 32psi RF: 32psi LR: 32psi RR: 32psi
Battery Inspection Comment: Dead battery + needs bedown
General Comment: Oil pressure sensor is leaking and must be replaced