

Truck Tractor Condition Report:

Equipment Information:

Unit No: 44886
Year: 2006
Make: Peterbilt
Model: 357
VIN/SN: 1NPALT0X06N644886

Miles/Hrs.: 684624/11249

Engine Information:

Year: 2006
Make: Cummins
Model: C10
SN: _____
HP: _____

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: _____ Number of Cylinders 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: _____ Notes: _____

Suspension: Spring Notes: _____

Wheel Base: in. _____

Axle Weight Ratings (LBS): GVWR: 66,000 Front Axle: 220,000 Rear(s): 44,000

Tire Size: Front: 295/75R22.5 Rear(s): 295/75R22.5

Comments: _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____