Truck Tractor Condition Report:

		Equi	pment Infor	mation:			
Unit No:	56141		_	Engine Information:			
Year:	2005		Year:_				
Make:	Wester Star		Make:	Mercedes			
Model:	4900		Model:		HP:		
VIN/SN:	5KKSAECY25PN56141		SN:				
KM/Hrs.:	921368		Fuel Type:	Diesel			
Equipment Condition:							
Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.						on.	
Inte	rior Condition:	Good - Damage is limited to normal wear and minor scratches.					
Exte	erior Condition:	Good - Minor dings and scratches					
AC/H	eat Functional:	Yes					
Leaks Present:		Not Seen Engine D	isplacement:	8.9L N ui	mber of Cylinders	6	
Sleeper (if Applicable):		Length:	# of Bunks: _	A	ux Power Unit?		
Additio	nal Equipment:						
Transmission:							
	smission Make:	Eaton Fuller					
Auto / Manual:		Manual		Numbe	r of Speeds:		
Truck Moves FWD/REV:		Both					
	Comments:						
			Chassis:				
	Frame Rails:		Chassis.	Note	·		
	Suspension:			Note	-		
	Wheel Base:		in.	Note). 		
Avla Waigh	-	GVWR: 33,000	_'''. Front Axel:		Rear(s):		
Axle Weight Ratings (LBS): Tire Size:		Front: 33,000	_ ITOIIL AXEI	Rear(s			
	Comments:	110IIC.			,·		
	comments.						
		Sned	cialized Equi	nment:			
Туре:			Details:	omend.			
Type:			Details: Details:				
, i							
Notes:							
Notes:							
_							