

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Excavator

Other: _____

Unit No: N/A

Year: 2014

Make: CATERPILLAR

Model: 329EL

VIN/SN: CAT0329EEZCD00762

Miles/Hrs.: 11614

Engine Information:

Year: 2014

Make: CAT/PERKINS

Model: C7.1 ACERT

SN: C7R12354

HP: 216

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Very Good - Starts and operates with no known mechanical defects.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Yes

Additional Equipment: N/A

Chassis:

Powertrain Type: _____

Propulsion Type: Track, Metal

Track Condition: Good - Track condition shows normal wear from use

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

I observed the unit in operation and saw no issues. It performed properly in movement, hydraulics and rotation.