

## GovDeals Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>2009</u> Make <u>JOHN DEERE</u> Model <u>5075M</u>		
VIN: <u>L V S 0 7 5 M 1 6 0 1 9 5</u> Title Restriction: <input type="checkbox"/> Y <input type="checkbox"/> N		
Odometer: <u>2 7 5 7</u> <input type="checkbox"/> Miles <input type="checkbox"/> Kilometers Odometer Accurate <input type="checkbox"/> Y <input type="checkbox"/> N		
Long Description: This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Runs/Driveable <input type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: <u>L, V</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition		
Repairs needed: This vehicle was maintained every <u>250</u> <input type="checkbox"/> Days <input checked="" type="checkbox"/> Hours <input type="checkbox"/> Miles		
Date Removed From Service: <u>10-12-2025</u> Maintenance Records: <input checked="" type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection		
<u>Transmission:</u> <input type="checkbox"/> Automatic <input type="checkbox"/> Manual Speed Condition: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition		
Repairs Needed: <u>Drivetrain:</u> <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition:		
<u>Exterior:</u> Color: _____ Windows: <input type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____ Minor: <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: _____ Tread: _____ #Flat _____ Hubcaps #_____		
Major Damage to: _____ Additional Damage: _____ Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input type="checkbox"/> Have been Removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Emergency equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
<u>Interior:</u> Color _____ <input type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: _____ Damage to Dash/Floor: _____		
Radio: <input type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD <input type="checkbox"/> AC (Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown) <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual <input type="checkbox"/> Cruise Control <input type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Windows <input type="checkbox"/> Door Locks <input type="checkbox"/> Seats		
Additional Equipment: <u>FRONT END LOADER WITH BUCKET</u>		
Manufacturer _____ Model _____ Serial # _____		
<input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand _____ <input type="checkbox"/> Hitch: Type _____		
Location of Asset: _____ For more information contact: _____		
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		

**Hartland Golf Course**  
**EQUIPMENT MAINTENANCE RECORDS**

**Property No:** PW37  
**Description:** JD 5075M TRACTOR  
**Model:** 5075M  
**Serial:** LV5075M160195  
**Mfgr:** JOHN DEERE

**Hours/Odometer:** 109  
**Group Code:** TRACP

**Notes:**

	Hours/Miles	Labor Hours	Labor Cost	Parts Cost	Fuel Cost	Total Cost	Cost Hr/Mi
YTD:	110.50	11.80	\$63.00	\$1,213.91	\$0.00	\$1,276.91	\$11.56
Life:	109.00	11.80	\$63.00	\$1,213.91	\$0.00	\$1,276.91	\$11.71

Date	Work Order	Hrs/Mi	Labor Hrs	Labor Cost	Parts Cost	Work Description
10/7/2025	0	2756	0.00	\$0.00	\$0.00	SERVICED
4/16/2025	0	2752	0.00	\$0.00	\$0.00	OILAFFFLUBE
7/12/2024	0	2745	0.00	\$0.00	\$342.00	L&R OUTTER TIE RODS
7/12/2024	0	2745	0.00	\$0.00	\$210.00	STEERING HOSES
3/22/2024	0	2739	0.00	\$0.00	\$0.00	SERVICE
3/22/2024	0	2739	0.00	\$0.00	\$300.00	TCOVER SEAL
3/7/2023	0	2672	0.00	\$0.00	\$0.00	SERVICED
4/28/2022	0	2645	0.00	\$0.00	\$0.00	SERVICED,FF,AF
6/2/2021	0	2558	0.00	\$0.00	\$0.00	SERVICED,LUBED
5/26/2021	0	0	0.00	\$0.00	\$0.00	FUEL FILTER
3/9/2020	0	2241	0.00	\$0.00	\$0.00	SERVICED,FF,AR,OIL
8/29/2019	0	2154	0.00	\$0.00	\$0.00	FUEL FILTER
3/11/2019	0	1943	0.00	\$0.00	\$0.00	SERVICED,FF,AIR
2/23/2018	0	1708	0.00	\$0.00	\$0.00	OIL AIR FUEL
1/13/2017	0	1501	4.00	\$0.00	\$0.00	OLF,AIR ,FUEL
11/17/2015	0	1285	6.00	\$0.00	\$236.02	SERVICED AND WATER PUMP
9/13/2011	242	0	0.00	\$0.00	\$0.00	OIL CHANGE-OIL CHANGE 588 D
4/1/2011	248	109	1.80	\$63.00	\$125.89	