

Vehicle Test Detail

Station ID: 1P051194	Station Name: KWIK KAR-BENBROOK	Overall Result: Pass
TAS Id: ES901136	Test Type: Safety Only	TX DOT #:
Test Date: 05/16/2024	Safety Result: Pass	Waiver Number:
Test Start Time: 11:01:33	Emission Result:	Reg Fee Code: 1YR
Test End Time: 11:02:25	Gas Cap Result:	Test Record No.: 1537
<hr/>		
VIN: 3C7WRKBL0LG289533		License Plate: 1444239
Model Year: 2020	Make: DODG	License Type: Texas Plate
Vehicle Type: Truck/Van/Bus/Sports Utility	Body Style: Pickup/Truck Tractor	Model: RAM 4500
Engine Size: 0	Trans. Type:	No. Cylinders:
GVWR Type: Heavy	Act. GVWR: 16500	Odometer: 180598
Fuel Type: DIESEL		Ignition Type:
		Dual Exhaust:
Inject Carburetion:		Decal No.:
Sticker No.:	Inspection Expiration Date:	
<hr/>		
Gas Cap Result 1:	Gas Cap 1 Testable:	Gas Cap 1 Missing:
Gas Cap Result 2:	Gas Cap 2 Testable:	Gas Cap 2 Missing:

Safety Test Information

Safety Test: Initial	Type: 1 Yr. Windshield (Safety Only)	
Horn: Pass	Exhaust: Pass	School Buses:
Windshield Wipers: Pass	Emissions System: Pass	School Bus Signs:
Mirrors: Pass	Beam Indicator: Pass	Fire Extinguisher:
Steering System: Pass	Tail Lamp: Pass	Hazard Warning Lights:
Seat Belts: Pass	Stop Lamp: Pass	Convex Crossover Mirror:
Service Brake System: Pass	License Plate Lamp: Pass	Mud Flaps/Safety Guards:
Parking Brake System: Pass	Rear Reflector: Pass	Window Tint/Sun Screen: Pass
Tires: Pass	Turn Signals: Pass	Back-up Lamps:
Steering Axle Tires:	Turn Sig/Ind Lamp: Pass	Coupling Devices:
All Other Tires:	Headlamps: Pass	Fuel System:
Wheel Assembly: Pass	Clearance Lamps:	Suspension:
Master Cylinder: Pass	Side Marker Lamps:	Frame:
	Cab Lamps:	Windshield:
	Side Reflectors:	Reflective Tape:

Repair Information

Repair Group:	
Repairs Performed:	
Repair Cost YIS: \$0.00	Rep.ID:
Repair Cost NRF: \$0.00	Safety VI30A:
Repair Cost RRF: \$0.00	
Total Parts Cost MSP: \$0.00	
Overall Repair Costs: \$0.00	
Total Emission Costs: \$0.00	
Total Safety Costs: \$7.00	
Overall Costs: \$7.00	