

Vehicle Condition Report:

Vehicle Information:

Vehicle Type:

Other: Bus

Unit No: 73742

Year: 2006

Make: MOTOR COACH INDUSTRIES

Model: D4505

VIN/SN: 1M86DMPA36P057203

Miles: 592718 HR25261

Engine Information:

Year: 2006

Make: DETROIT

Model: D60

SN: _____

Fuel Type: Diesel

Vehicle Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Condition Comments: Under body rust

Engine Displacement: 12.7 Liters. Crankshaft (V, Inline, Boxer) Inline Cylinders: 6

Power Windows: Yes

Power Locks: _____

Air Conditioner / Heat: Yes

AC / Heat Functional: Yes

Transmission: Automatic

Number of Manual Speeds: 6

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): _____

Functional: _____

Additional Equipment: _____

Chassis:

Suspension: Air

Notes: _____

Wheelbase: 318

GVWR: _____

Front: 16000 Rear(s): _____

Tire Size: _____ Front: 11r22.5

Rear: 11r22.5

Comments: _____

Cargo / Passenger Vans

Passenger Van Seating: _____ Rows _____

Cargo Van Box Dimensions:

Length: _____

Width: _____

Height: _____

Additional Notes: 1 bathroom 6 tvs